

COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Housing and Public Works under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "(c) State of Queensland (Department of Housing and Public Works) 2020, licensed under the CC BY 4.0 Licence, prepared by Arup". This licence does not apply to logos or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://ggd.org.au/>

This log has been contributed to the Queensland Geotechnical Database with the permission of Arup.

CORED BOREHOLE RECORD

HOLE

BH8

SHEET 3

OF 3

PROJECT LANG PARK STADIUM REDEVELOPMENT

LOGGED BY VL

DATE/S 20.10.00

CONTRACTOR SP & KF CHRISTENSEN

ANGLE Vertical

DRILL MODEL JACRO 350

BEARING -

MOUNTING 4x4 TRUCK

DIAMETER 50/75/100mm

GROUND LEVEL -RL 6.75m

LOCATION See Figure 2

DRILLING			STRATA		LEGEND	MATERIAL DESCRIPTION	WEATHERING	ESTIMATED ROCK STRENGTH			FREQUENCY (per m)	SPECIFIC			GENERAL DESCRIPTION
CASING RUN, REC. (%)	WATER	SAMPLE TEST	R.L.	DEPTH				EL	M	LEH		TYPE	ANGLE	THICKNESS (mm)	
			AHD	m											
100%		Is(50) = 1.89				PHYLLITE: Dark blue grey with white foliation bands	SW					Jo	30	0	
100%												Jo	10	0	
100%												Jo	45	0	
100%						Quartz seam 70mm thick						Cr	5	0	XW rock iron stained
100%				9								Cr	0	70	
100%												Cr	0	25	large fragments iron stained
100%				10								Cr	0	20	
100%												Cr	0	0	
100%												Cr	0	5	orange stiff clay
100%												Cr	0	5	
100%												Cr	0	35	
100%												Jo	0	0	
100%												Jo	0	0	iron stained
100%												Jo	0	0	iron stained
100%				11								Jo	0	0	
100%												Cr	0	5	iron stained
100%												Jo	10	0	
100%												Jo	20	2	staggered
100%												Jo	0	0	iron stained
100%												Cr	0	5	iron stained
100%												Cr	0	10	
100%												Cr	0	5	
100%				12								Jo	0	3	DW rock
100%												Cr	0	5	DW rock
100%												Jo	10	0	staggered
100%												Cr	15	5	some angular crushed rock
100%												Jo	0	0	
100%												Jo	0	0	
100%												Jo	0	0	
100%				13								Cr	20	10	
100%			-6.50	13.25		BH8 END						Jo	30	0	
				14											
				15											

NOTES


- 1) No groundwater encountered prior to washboring at 4.5m
- 2) Standpipe monitoring well installed to 13.25m

TYPE OF DISCONTINUITY

Jo JOINT
Be BEDDING PLANE PARTING
Fo FOLIATION PARTING
Cl CLAY SEAM
We WEATHERED SEAM
Cr CRUSHED SEAM
Sh SHEARED ZONE
Qr QUARTZ SEAM

JOB


12215



Borehole 8

6m - 12m

Box 1 of 2



Borehole 8

12m - 13.25m

Box 2 of 2