

COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "*(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence*". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>



FOR GEOTECHNICAL TERMS AND
SYMBOLS REFER FORM F:GEOT 017/6-2010

REFERENCE No **H11130**

JOB No 232/10A/2 HEIGHT DATUM AHD BEARING DATE COMPLETED 25/07/11 DRILLER Drillsure Pty Ltd

DEPTH (m)	R.L. (m)	AUGER CASING WASH BORE CORE DRILLING	RQD () %	CORE REC %	SAMPLE	MATERIAL DESCRIPTION	LITHOLOGY	USC	WEATHERING	INTACT STRENGTH	DEFECT SPACING (mm)	GRAPHIC LOG	ADDITIONAL DATA AND TEST RESULTS	SAMPLES TESTS
0	76.40													
	76.20					TOPSOIL: Grey. Sandy SILT (Residual soil) Brown.								
							(ML)						Based on driller's logs only	
	75.50				A	SANDSTONE (HW): Brown, medium grained.								
1							HW						24,28,30/100 N>50	SPT
	74.40					SANDSTONE (HW) Brown/grey, medium to coarse grained, massive, low to medium strength. Defects: -Joint at 40°-45°(2/m) -Joint at 60-65° (1/m) Defects are close to medium spaced. Defects are planar, tight or open, slightly rough, clay infilled, iron stained. Pebbles throughout up to 50mm.						XW Clay Seam		
2			(0)				HW						J, 40°, Pl, O, Clnf J, 65°, Pl, T, Clnf Is(50) = 0.38MPa Is(50) = 0.40MPa	x o
3			100 (38)			SANDSTONE (MW): Brown/grey, medium to coarse grained, massive, high strength, indurated and/or slightly metamorphosed. Defects: -Joint at 20°-25° (1/m) -Joint at 40°-45° (2/m) -Joint at 50° (<1/m) -Joint at 60°-65° (~1/m) Defect spacing is generally medium. Defects are planar, tight or closed, slightly rough, clay infilled, iron stained. Pebbles throughout up to 50mm.						J, 65°, Pl, T, Clnf J, 45°, Pl, T, Clnf J, 45°, Pl, T, Clnf J, 60°, T, Clnf DD = 2.48t/m ³ ; MC = 1.4%; UCS=12.5MPa J, 25°, Pl, O, Clnf J, 50°, Pl, O, SR, Clnf Is(50) = 2.02MPa Is(50) = 3.14MPa	x o	
4	72.98		100 (73)				MW							
5			100 (77)											
6			100 (26)											
7			100 (59)											
8			100 (60)											
9	67.64					SANDSTONE (SW): Grey/brown, medium to coarse grained, massive, very high strength, indurated and/or slightly metamorphosed. (See over)								
							SW						J, 25°, Pl, O, Clnf, FeSt J, 70°, Pl, T, FeSt J, 40°, I, O, Clnf, FeSt	x o

REMARKS _____

LOGGED BY
JA/DC

ENGINEERING BOREHOLE LOG

FOR GEOTECHNICAL TERMS AND
SYMBOLS REFER FORM F:GEOT 017/6-2010

BOREHOLE No BH C41
SHEET 2 of 2
REFERENCE No H11130

PROJECT Bruce Highway Upgrade (Cooroy to Curra) Section C
LOCATION Cut 10 COORDINATES 471499.6 E; 7094901.8 N
PROJECT No FG5799 SURFACE R.L. 76.40m PLUNGE _____ DATE STARTED 25/07/11 GRID DATUM MGA94
JOB No 232/10A/2 HEIGHT DATUM AHD BEARING _____ DATE COMPLETED 25/07/11 DRILLER Drillsure Pty Ltd

DEPTH (m)	R.L. (m)	AUGER CASING WASH BORING CORE DRILLING	RQD () %	CORE REC %	SAMPLE	MATERIAL DESCRIPTION	LITHOLOGY	USC	WEATHERING	INTACT STRENGTH						DEFECT SPACING (mm)						GRAPHIC LOG	ADDITIONAL DATA AND TEST RESULTS	SAMPLES	TESTS
										EH	VH	H	M	L	VL	EL	20	60	200	600	2000				
10	66.40					SANDSTONE (SW): Cont'd Defects: -Joint at 20°-25° (<1/m) -Joint at 40° (~1/m) -Joint at 55°-60° (1/m) -Joint at 65°-70° (<1/m) -Joint at 85°-90° (<1/m) Defects are generally medium spaced. Defect surfaces are generally planar, open or tight, slightly rough, iron stained, clay infilled. Pebbles up to 25mm throughout.																			
11				100 (83)																					
12				100 (72)																					
13				100 (45)																					
14				100 (63)																					
15				100 (63)																					
16	60.55			100																					
17																									
18																									
19																									
20																									

REMARKS _____

LOGGED BY
JA/DC

CORE PHOTO LOG - BH C41



Project Name:	BRUCE HIGHWAY UPGRADE - SECTION C		
Project No.:	FG5799	Date:	08/09/2011
Details:	Cut 10	Start Depth (m):	2.00
Reference No.:	H11130	Finish Depth (m):	15.85





CORE PHOTO LOG - BH C41

Project Name:	BRUCE HIGHWAY UPGRADE - SECTION C		
Project No.:	FG5799	Date:	08/09/2011
Details:	Cut 10	Start Depth (m):	2.00
Reference No.:	H11130	Finish Depth (m):	15.85



SCALE 1:5