

COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "*(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence*". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

MAIN ENGINEERING DEPARTMENT ENGINEERING BORE LOG
PROJECT: GATSBY RIVER

Form 232L (c)
(P) /3/79

Sheet 1 of 3

HOLE No. 15

REF. H 4956

DEPTH AHD

LOCATION: River 6 Km. West, 15° right of centerline.
N 31652 SEC. R 45565 S26

JOB No. 110/SLA/421 PROJECT No. 4/34 DATE 1/11/80 SURFACE RL +0.70

TYPE OF DRILLING	Hollow Auger	Casing	Depth	Casing	Depth
			(m)		(m)
			2.20 - 22.00		

ENGINEERING PROPERTIES		STRUCTURE	CORE REC %	Depth & R.L.	STRATA DESCRIPTION
Intact Strength	Defect Sourcing				
			GRAPHIC	R.D.	SOIL TYPE OR WEATHERING
				-1.50	
				0.1	
				(-2.10)	
				8.8	A1
				20	
				140	7.00
			(0)	8.9	HIGHLY WEATHERED
			55	8.4	grey, defects
				8.9.4	iron stained
				8.5	MODERATELY WEATHERED
				10.2	Fractured along horizontal "clint" containing numerous beds of black carbonaceous shale and grey shale to 1cm dark brown iron stained.
			(0)	10.0	

GEOL. ENGR.
APPR.

NOTE

MAIN ROADS DEPARTMENT, ENGINEERING BORE LOG

PROJECT GALLIVY JETTIES

LOCATION

Form 23ZL (d)

(P) /3/78

Sheet 2 of 7

HOLE No. JR (cont)

F.R.E. II 496

DATUM AHD

SURFACE RL.

JOB No.

PROJECT No. 1/154

DATE

TYPE OF DRILLING

Hollow Auger
CoringDepth (in)
Depth (m)

Casing

Depth (in)
Depth (m)

ENGINEERING PROPERTIES

Infill Strength
Defect Spacing

STRUCTURE

CORE REC
%
R.Q.D
(1 %)Depth &
R.L.
F.S.O.
10.0STRATA DESCRIPTION
SOIL TYPE LITHOLOGY
OR WEATHERING

Core Log	Depth (ft) (m)	Strata Description	GEOLOGIC	
			Top	Bottom
	(0) 0.0	(-42.4) 11.7	Moderately weathered	
Coal	(33) 100	(-13.5) 11.7	Frequently weathered Grey, bedding dips 0-10°, rust defect parallel to bedding clay coated	
Clayey seams	{			
Coal	(59) 100			
Coal	(15) 100			
soft clayey band				
Coal	(95) 100			
		16.8		
		-19.2	Slightly weathered Grey massive rock defects rare	
High angle defn fresh surface	(93) 100			
Sandstone band				
	(95) 100	19.8		
		-20.2		

REMARKS

GEOL.
APPR.

ENGR.

GP

Core Log

WEATHERING

Extremely
WeatheredModerately
WeatheredWater
Level

NOTE

Sheet 3 of 3
HOLE No. 56 (cont.)

REF. RA/56

DATE 1/10/80

SURFACE RL

LOCATION

JOB NO.

PROJECT No. 1/80

DATE

TYPE
OF
DRILLING

Hollow Auger

Depth
(m)
Depth
(ft)

Casing

Depth
(m)
Depth
(ft)

Coring

ENGINEERING PROPERTIES		STRUCTURE	CORE REC % R.Q.D. (1%)	Depth & P.L. () 1.50 20.0	STRATA DESCRIPTION	
Impact Strength	Defect Spacing				SOIL TYPE OR WEATHERING	LITHOLOGY
				-22.4	SLIGHTLY WEATHERED Grey with clay matrix, contains numerous coal seams 1 to 10mm	
			(98) 100		Bedding dips 0-10° Defect rare	
			(83) 100			
				-23.15		
				-25.55	SLIGHTLY WEATHERED Grey, fissile rock vertical defect with clay infilling	
		Shear zone, soft clayey sand with numerous iron pyrite sulphide	(55) 100			
				-24.4		
				-26.0	SLIGHTLY WEATHERED Grey with clay matrix contains thin shale interbeds to 2cm	
			(85) 100		Bedding dips 0-10° rare defects parallel to bedding Defect surfaces fresh	
				-27.15		
				-29.55	SLIGHTLY WEATHERED Interbedded sandstone and shale sequence Defects rare	
		Closely spaced steeply dipping 30-45° defect surface fresh	(78) 100			
			(95) 100			
				-31.0	END OF BORE	

REMARKS

GEOLOGIC

APPENDIX

NOTE

Extremely
Moderately
Weak

(c) State of Queensland (Department of Transport and Main Roads) 2020, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.