COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/

FORM 23 ZL (c) -/9/80

PROJECT

FREDERICK STREET OVERPASS FOUNDATION INVESTIGATION

34470.549 E, 29394.154 N, (Ch. 176, 2mR of control)

Sheet 1 of 2


HOLE No. 5

H 5852 REF. No.

AHD DATUM

DATE 7-4-87

SURFACE R.L. 15.22



Core Loss | WEATHERED CONDITION

Extremely Weathered Highly Weathered

Moderately Weathered Slightly Weathered Water Level ∇

GEOL. ENGR. APPR.

> NOTE FOR TERMS AND SYMBOLS REFER TEST METHOD Q 188 - 1980 MATERIALS TESTING MANUAL

FORM 23 ZL (d) -/9/80

PROJECT

LOCATION

FREDERICK STREET OVERPASS FOUNDATION INVESTIGATION

of Sheet 2 2

HOLE No.

5 5852

DATUM

REF. No.

JOB		0.	PROJECT No.	DATE	SURFACE R.L.		
CASING	(m)	1:50	STRATA DESCRIPTION	R.Q.D.	Log		ENGINEERING PROPERTIE
50"	TH (R.L	SOIL TYPE	7 / 10/		STRUCTURE	INTACT DEFECT STRENGTH SPACING
OTHE	DEPTH	5.22	OR WEATHERING	REC. %	GRAPHIC		STRENGTH SPACING
			Clayey SAND	G23			1111111111
I	1-		Minor gravel present below 10.0m		8		
	-	3.72		30*			4
ľ	2-	3.22	HIGHLY WEATHERED Clayey throughout	H 90			
			HIGHLY WEATHERED Clayey throughout MODERATELY WEATHERED Highly, siliceous throughout, quartz veining common and contorted: foliation obscure. Defects div	73	1	High angle defect, brown ironstained.	
	3-	0.	No at low (<20°) and		A Day of		*
	4-	1.17	high angles brown ironstained on defections	97	1	981	
			END OF HOLE				7
	5-						
	6-						
	7-		7				
	-						
	8-						
	9-						T
	-						

REMARKS X

Diametral Point Load



Core Loss

WEATHERED CONDITION





Water Level ∇

GEOL ENGR. APPR

> NOTE FOR TERMS AND SYMBOLS REFER TEST METHOD Q 188 - 1980 MATERIALS TESTING MANUAL

