COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/



ENGINEERING BORELOG

FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM F873 NOV/87

SHEET : 1 OF 2

REFERENCE No : H7164

PROJECT : PEDESTRIAN OVERPASS OVER GATEWAY ARTERIAL AT DEAGON PIER 5 -38222E 47658N LOCATION PROJECT No : 1-694 SURFACE R.L. : 5.27 DRILLER: DALY BROS : 140/U13c/41 DATUM : AHD DATE DRILLED : 25/2/93 ROD INTACT DEFECT R.L. Ξ ADDITIONAL DATA STRENGTH SPACING ()% 0 (m) MATERIAL DEPTH AND SRAPHIC SAMPLES CORE DESCRIPTION TESTS CORE TEST RESULTS 28888 REC% EE-2 5 0 CLAY Grey, with some brown mottling, firm, moist alluvium. medium to high plasticity. some sand content and plant roots in **U48** top 1.5m. CH N=7 SPT 2.07 BASALT GREY, FINE GRAINED, MASSIVE, VOLCANIC ROCK. N=35 SPT Grey-green, with engineering propeties of a dense clayey sand. ΧV Rock structure clearly visible. 0.77 Green-black, with high strength rock SPT N=26/130 HW kernels in part. 0.27 frequent clayey bands Grey,open defects generally low angle , clay coatings on defect planes. core also contains many semi-closed brown stained defects. 占clay band 100 MU subvertical defect 100 -8 : -3.03 CLAY Red to brown, very stiff, moist, residual medium to high plasticity. CH 93 10 -4.73 LOGGED BY REMARKS :



ENGINEERING BORELOG

FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM F873 NOV/87

BOREHOLE No : 2

SHEET : 2 OF 2

REFERENCE No : H7164

PROJECT : PEDESTRIAN OVERPASS OVER GATEWAY ARTERIAL AT DEAGON

LOCATION : PIER 5 -38222E 47658N

PROJECT No : 1-694 SURFACE R.L. : 5.27 DRILLER : DALY BROS

OB NO : 140/U13C/41 DATUM : AHD DATE DRILLED : 25/2/93

(m) H4430 10-4.73	AUGER OFILLING CORE DRILLING CASING OTHER	RQD ()% CORE REC%	CORE LOSS	MATERIAL DESCRIPTION CLAY as before	요 XE WEATHERING	INTACT STRENGTH	DEFECT SPACING (mm) 0002	GRAPHIC LOG	ADDITIONAL DATA AND TEST RESULTS N=21	SAMPLES SAMPLES TESTS
-7.18 -13 -14 -15 -16 -17 -18				END OF HOLE						

REMARKS :

LOGGED BY

(c) State of Queensland (Department of Transport and Main Roads) 2020, CC BY 4:0: Please note copyright and limitation of liability notices on attached cover pa

PEDESTRIAN FOOTBRIDGE AT DEAGON

START 5.0 M

HOLE 2 H 7164

1 OF 1

MARCH 93

