

## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Housing and Public Works under the [Creative Commons Attribution 4.0 Licence](https://creativecommons.org/licenses/by/4.0/) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "(c) State of Queensland (Department of Housing and Public Works) 2020, licensed under the CC BY 4.0 Licence, prepared by Arup". This licence does not apply to logos or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://ggd.org.au/>

This log has been contributed to the Queensland Geotechnical Database with the permission of Arup.



PROJECT LANG PARK STADIUM REDEVELOPMENT

LOGGED BY	PBF
DATE/S	2.11.00

CONTRACTOR SP & KF CHRISTENSEN

ANGLE	Vertical
-------	----------

DRILL MODEL JACRO 350

BEARING -

MOUNTING 4x4 TRUCK

DIAMETER 50/75/100mm

GROUND LEVEL ~R/L 7.0m

LOCATION See Figure 2

[illegible]

## NOTES

- 1) No groundwater encountered prior to washboring at 3.0m
- 2) Standpipe monitoring well installed to 11.45m

TYPE OF DISCONTINUITY

Jo	JOINT
Be	BEDDING PLANE PARTING
Fo	FOLIATION PARTING
Cl	CLAY SEAM
We	WEATHERED SEAM
Cr	CRUSHED SEAM
Sh	SHEARED ZONE
Qr	QUARTZ SEAM

JOB

12215

# CORED BOREHOLE RECORD

HOLE

**BH19**

SHEET 3

OF 3

PROJECT LANG PARK STADIUM REDEVELOPMENT

LOGGED BY PBF

DATE/S 2.11.00

CONTRACTOR SP & KF CHRISTENSEN

ANGLE Vertical

DRILL MODEL JACRO 350

BEARING -

MOUNTING 4x4 TRUCK

DIAMETER 50/75/100mm

GROUND LEVEL -RL 7.0m

LOCATION See Figure 2

DRILLING			STRATA			MATERIAL DESCRIPTION										DISCONTINUITIES				
CASING RUN, REC. (%)	WATER	SAMPLE TEST	R.L.	DEPTH	LEGEND	ROCK TYPE Colour, Grain Size, Structure, Minor Components	WEATHERING	ESTIMATED ROCK STRENGTH			FREQUENCY (per m)	SPECIFIC			GENERAL DESCRIPTION					
			AHD	m				EL	M	EH		TYPE	ANGLE	THICKNESS (mm)						
100%						PHYLLITE: Dark blue grey with white foliation bands					1									
100%		Is(50) = 0.65		9		Colour grading to Dark blue grey foliated white, some high strength quartz veins	SW				3									
100%		Is(50) = 0.68				Quartz seam 40 mm thick					10									
100%				10																
100%																				
100%				11																
100%																				
100%																				
100%																				
100%		Is(50) = 2.3	-5.00	12.00		BH19 END	DW SW													
				13																
				14																
				15																

NOTES


- 1) No groundwater encountered prior to washboring at 3.0m
- 2) Standpipe monitoring well installed to 11.45m

TYPE OF DISCONTINUITY

Jo JOINT  
Be BEDDING PLANE PARTING  
Fo FOLIATION PARTING  
Cl CLAY SEAM  
We WEATHERED SEAM  
Cr CRUSHED SEAM  
Sh SHEARED ZONE  
Qr QUARTZ SEAM

JOB

**12215**



**Borehole 19**

**6m - 12m**

**Box 1 of 1**