#### **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

#### **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <a href="http://qgd.org.au/">http://qgd.org.au/</a>



# ENGINEERING BORELOG

FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM BQF 075:191/95

BOREHOLE No : 202
SHEET : 1 OF 2

REFERENCE No : H8147

PROJECT					•••••	•••••	••••••	•••••			
COCATION				163438.958N	•••••	•••••			<b>D</b> A1	V 2007HEDG DTV 1 TD	
JOB No				SURFACE R.L. : 22.58  DATUM : AHD						12/97	
			Т		1	INCTACT.	DEFFOR		ı		T
E R.L.	>	QD	1		9	STRENGT	H SPACING (mm)	F00	AD	DITIONAL DATA	
 DEPTH 	III   `			MATERIAL			(mm)	כ דע		AND	ဖ္လ
		ORE	SAMPLE	DESCRIPTION			8	GRAPHIC	ļ ,	EST RESULTS	SAMPLES
0 22.58	₹ÖĞĞ R	EC*	§ S		S I	₩ ₩ ₩ ₩	88888	GR/			SAN
				PHYLLITE: YELLOW BROWN TO DARK GREY FINE TO MEDIUM GRAINED FOLIATED METASEDIMETARY ROCK. BEDDING 10-70 DEGREES AND IRREGULAR TO CONTORTED; ALTERNATIVE DARK (MICA) & LIGHT (QUARTZ) LAYERS. FREQUENT CONCORDANT AND DISCORDANT QUARTZ VEINS.	нw				Driller's	s log only	- - - -
	1	0)							₽78 <u>*</u> 83572	26,30/50 N=>50	SPT -
20.68	🛭 🗎	0)						7 - 12	Broken zo	one	-
2 20.00			<b>*</b>	MW:		+			Coargo gr	ained quartz vein	-
				Partly or completely red brown ironstaining throughout.			1		1	ained quartz vein	
- - -	E333 - 1	0) 19		Rock tends to break along bedding partings during handling.			‡	) 1 y 1	Broken zo	one	-
-3			▓	DEFECTS -70 degrees,	MW		<b>‡</b>		Coarse gr	ained quartz vein	-
	[33]	.00		-30 to 40 degrees, -40 degrees (cross cutting)					Coarse gr F/D=09875 Broken zo	ained quartz vein	
18.58	F331 1	3)							Coarse gr	ained quartz vein	
			▓	SW: Red-brown ironstaining only along defects.						Is (50)=0.23MPa	×
5	1881 . T	(2) .00							Broken zo F/D=164/4	5.76 one 3	IICS -
6	1993	(O) (O)									
15.98							‡	$\subseteq$	8/1/98		-
7					sw				F/D=310/4	Is(50)=0.11MPa	×
F							<b>∓</b> [			3.23	-
- - 8	1888	.00							Broken zo	one Is(50)=0.24MPa	x -
									Coarse gr	Is(50)=0.23MPa rained quartz vein	x -
9	F33	10)								Is(50)=0.35MPa	× -
							<u> </u>				1
10 12.58							#		E/D=099/4		-
REMARKS	•••••		••••	predominently along foliation planes duri	ng I	Point Lo	d Test			LOGGED BY DI <b>SS</b>	

(c) State of Queensland (Department of Transport and Main Roads) 2020, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.



# ENGINEERING BORELOG

FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM BQF 075:191/95 BOREHOLE No: 202

SHEET: 2 OF 2

REFERENCE No: H8147

PROJ	ECT	:s	OUTH E	AST	TRANSIT PROJECT-SECTION 2								
JOCA	TION	: 3	219.54	5E	163438.958N								
PROJ	ECT No	: C	60117		SURFACE R.L. : 22.58						LER :	DALY BROTHERS PTY LTD	
JOB			50302CI		DATUM : AHD								
_				• • • •		••••							
(E)	R.L.	<u>o</u>	RQD	l		$  \  $		INTACT	DEFECT SPACING (mm)		1	ADDITIONAL DAMA	
5	(m)	<u> </u>	( )%		MATERIAL	l l	S)	STRENGTH	SPACING	9		ADDITIONAL DATA	1 1
Ħ		BBII		۱, ۳	1		띫		(mm)	<u>⊇</u>	1	AND	S S
			CORE	SAMPLE	DESCRIPTION	ြပ	Ē,		20888	GRAPHIC LOG		TEST RESULTS	SAMPLES
10	R.L. (m)	₹88₽	REC*	SA		nsc	×۲	ı>∓ <b>∑</b> ⊣>	200 - 200 - 200 - 200 - 200 - 200	GR			SA
‡	12.28		(63) 100		SW: As above	SW	,						1
:		1001	100		END OF HOLE		+		- : : :				-
-					END OF HOLE		1	7	-				=
ΕÌ							1	· : : : <del>]</del>	[ : , ·		1		]
- 1 <b>1</b>							- {	-	<del>[</del>				]
	1	: : .				1	-	1	·		1		
<u></u>	- 1					l	Ì		]		1		1 1
ţ		1				Ì	Ţ	1	<u> </u>				l i
12		i -						‡					1
[12		: : :					Į	7	F :				7
E								: · · · · · · · · · · · · · · · · · · ·					]
- 1						l	-	1	- :				-
t	- 1					l	1	‡			1		
-13							-	4	-				1 4
	-	: :						+	-				l i
Εl	-						1	3	-				E l
ΕÍ						l	1	: · · · · · · · · · · · · · · · · · · ·			1		1 1
	i					1	ı	:: ‡	:				
-14	ļ						-	4			1		7
<b>;</b>		:		l			-	1 1 1	: ]		1		1 1
FΙ							-	1	-				1 -
Εl							-				1		]
- - 15	1					l	1	= =	_				1 4
	-	111					- [	+	- : :				
<b>[</b> ]	- 1						-	1			1		1 1
Εl	- 1						1	E	-				
ΕI	- 1					1	-	· : I	- :		1		1 1
-16	1	. : .				1	1	1	- )		1		
t l	- 1	11:				l	1		:				1 1
- 1	- [						1	4			1		-
-16		. :						1	[ ]				] }
ار,							1	. i : i : i	_ :				
<u> </u> -							-	1	<u> </u>				‡
<b>;</b>								+ + +					
F								1 1 1 1	-				l I
[		1 1 1					-	<u> </u>					]
- 18								-	- :				-
								: :	<u> </u>				‡
-							1	4	-				-
<b>;</b>		: : .					ļ	- : 1	:				]
Ē.,		: : .						3	_				]
[ 19				1			1	<b>.</b>	<u> </u>				
		: :						· · · · · · · · · · · · · · · · · · ·					‡
F								1111	- : I				1 4
-								: : : :	.				1
- 20				L								LOGGED BY	

REMARKS : \*See attached sheet for defect descriptions.

Some of the defect data were extracted from BIPS.

LOGGED BY DISS

(c) State of Queensland (Department of Transport and Main Roads) 2020, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.



#### **DEFECT DESCRIPTIONS OF BORELOGS**

[FOR GEOTECHNICAL TERMS AND SYMBOLS

REFER FORM BQF 075:191/95]

BOREHOLE NO :	202
SHEET :	l of l
REFERENCE NO:	H8147

**PROJECT** 

JOB NO

**SOUTH EAST TRANSIT PROJECT - SECTION 2** 

LOCATION

3219.545E

PROJECT NO

163438.958N

C60117 SURFACE R.L

22.59

DRILLER

: DALY BROTHERS PTY LTD


650302CN AHD DATUM DATE DRILLED : 2/12/97

DEPTH	DEFECT TYPE	DIP(Degrees)	PLANARITY	ROUGHNESS	APERTURE	WALL ALTERATION	OTHER
2.47	J	20	Ir	R			_
2.6	J	20	Ir	R			_
2.8	J	69		R			
3.08	J	60	Ir	R			
3.5	J	70 & 10	Ir				
3.6	J	42					
3.86	J	45	Ir	R			
3.99	J	35	Ir	R			
4.02	J		Ir	R			
5.2	J	45	Ir	,			
5.75	J	60		R			_
5.98	J	75		Sm			-
6.06	J	80					Sm
6.61	J	43	Ir				
7.15	J	25		Sm			_
8.05	J	35	Ir			CoFeSt	
9.36		20	Ir				QZ
9.4	J	10	Ir			PFeSt	CI
9.47	J	10	Ir	R		CoFeSt	
10.1	J	10	[r				

#### **Abbreviations**


	ROUGHNESS	,	WALL ALTERATIONS		TYPE	OTHER		
R	Rough	FeSt	Iron Stained	J	Joint	P	Partly	
Sm	Smooth	W	Weathered	В	Bedding	QZ	Quartz Vein	
SL	SL Slickensided			BP	BP Bedding Parting		Completely	
				F	Folliation	ln	Incipient	
PLANARITY			APERTURE		Sheared Zone	SI	Sand Infil	
Pl	Planar	С	Closed	WS	Weathered Seam	Н	Horizontal	
St	Stepped	0	Open	CZ	Crushed Zone	V	Vertical	
Un	Undulating	F	Filled	SM	Secondary Mineralisation	Cl	Clay Intill	
Cu	Curved	Т	Tight	BZ	Broken Zone	Cn	Clean	
lr	Irregular			HFZ	Highly Fractured Zone			

NOTE: This sheet should be read in conjunction with appropriate Engineering Borelog.







## SOUTH EAST TRANSIT PROJECT BH 202 1.00 - 3.40 M




## SOUTH EAST TRANSIT PROJECT BH 202 3.40 - 5.80 M



### SOUTH EAST TRANSIT PROJECT BH 202 5.80 - 8.20 M



# SOUTH EAST TRANSIT PROJECT BH 202 8.20 - 10.30 M





#### SOUTH EAST TRANSIT PROJECT, SECTION 2

#### WATER PRESSURE TEST RESULTS

2 LUGEONS

Drill Hole:

202

Date:

2/12/97

----- ....

1

Test No:

From (m) To (m)

Length (m)

Test Section:

5

10.3

5.3

Groundwater Depth (m):

6.6

Gauge Height (m):

1.53

Hydrostatic Head (kPa):

81.3

Gauge Pressure (kPa)	Effective Pressure (kPa)	Test Duration (min)	Meter Start (litres)	Meter End (litres)	Water Loss (litres)	Leakage (1/m/min)	Lugeons
50	131.3	5	85	89.3	4.3	0.16	1.24
120	201.3	5	97.8	106.8	9	0.34	1.69
180	261.3	5	124.9	140.4	15.5	0.58	2.24

