### **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

### **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/



Project No.

Surface RL

FM2055

1.403


# REPORT ON CONE PENETROMETER TEST

Client MAIN ROADS - GATEWAY UPGRADE PROJECT TEAM

Project GATEWAY UPGRADE

Job Ref.

Location E 8874.668 N 171638.563 SET DATUM



NATA Accreditation Number 2302

NATA Endorsed Test Report

This document may not be reproduced except in full.

Program Version 4.03b (32bit)



# REPORT ON CPTu DISSIPATION TEST

Client MAIN ROADS - GATEWAY UPGRADE TEAM

Project GATEWAY UPGRADE


Job Ref. Project No. FG5389

Location E 8874.668 N 171638.563 Surface RL 1.403

Chainage Sounding CPTU160 Water Table 1.500 Start Depth 1.525

Test Date 10/02/2005

Remarks Dissipation Tests @ 3.5 & 5.5m



Depth (m)	3.58
Start Pressure (kPa)	156
Dissipation (%)	50
Dissipation Pressure (kPa)	88
Time for Dissipation (min)	6.8

		Cone Type	Piezocone	
Date	1/03/2005 /	Cone ID	3167	LN.
100	14 A	Factor "a"	0.580	V <sup>α</sup> τ <sup>N</sup>
Checked /5/	Factor "b"	0.014	NATA Accreditation Number 230	
Signatory Bally	Test Method	Q151A	NATA Endorsed Test Report	
	Report No.	FG5389/CPTU160/Q151A	This document may not be reproduced except in full.	



# REPORT ON CPTu DISSIPATION TEST

Client MAIN ROADS - GATEWAY UPGRADE TEAM

Project GATEWAY UPGRADE


 Job Ref.
 Project No.
 FG5389

 Location
 E 8874.668
 N 171638.563
 Surface RL
 1.403

Chainage Water Table 1.500

Sounding CPTU160 Water lable 1.500 Start Depth 1.525

Test Date 10/02/2005
Remarks Dissipation Tests @ 3.5 & 5.5m



Depth (m)	5.51
Start Pressure (kPa)	180
Dissipation (%)	30
Dissipation Pressure (kPa)	138
Time for Dissipation (min)	39.7

	1-27-2-2-2	Cone Type	Piezocone	
Date	1/03/2005	Cone ID	3167	N.
	and A	Factor "a"	0.580	N <sup>a</sup> zV
Checked /ST/	Factor "b"	0.014	NATA Accreditation Number 2302	
Signatory	Test Method	Q151A	NATA Endorsed Test Report	
	DAMPANO	Report No.	FG5389/CPTU160/Q151A	This document may not be reproduced except in full



# REPORT ON CPTu DISSIPATION TEST

MAIN ROADS - GATEWAY UPGRADE PROJECT TEAM

Project **GATEWAY UPGRADE** 

Job Ref.

Location E 8874.668 N 171638.563 SET DATUM Chainage

CPTU160 Sounding Test Date 02/11/2004

Client

Remarks Dissipation Test at 7.0m

Water Table was not measured and is assumed.




Project No. FM2055

Water Table 2.500

Start Depth 0.000

1.403

Surface RL



Depth (m)	7.00
Start Pressure (kPa)	219
Dissipation (%)	50
Dissipation Pressure (kPa)	132
Time for Dissipation (min)	43.0

		Cone Type	Piezocone
Date	08/11/2094	Cone ID	3167
	91	Factor "a"	0.580
Checked	13/1	Factor "b"	0.014
	DOM 12	Test Method	Q151A
Signatory	AND MAN	Report No.	FM2055/CPTU160/Q151A

