

## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "(c) *State of Queensland (Department of Transport and Main Roads) 2022, licensed under the CC BY 4.0 Licence, prepared by Insitu Geotech Services*". This licence does not apply to logos or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.


Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

This log has been contributed to the Queensland Geotechnical Database with the permission of Insitu Geotech Services.

# CONE PENETROMETER TEST RESULT

Department of Transport & Main Roads  
Bruce Highway Upgrade Project D  
Gympie QLD

## CPT-D-021



Job Number : G14-10-08  
Test Date : 29/10/2014  
DGPS Position :  
DGPS Format : WGS 84  
Rig : Tough Tommy  
Cone Number : C10CFIIP.C12025  
Predrill Depth : 0.00m  
Dissipation Tests @ : N/A  
Terminated Due To : Equipment at Risk

Tested By : Ellen O'Rourke  
Test Class : IGS-1  
Checked By : Tony Hitchcock

Insitu  
Geotech  
Services  
Pty Ltd

# IGS