

## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Housing and Public Works under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "(c) State of Queensland (Department of Housing and Public Works) 2020, licensed under the CC BY 4.0 Licence, prepared by Arup". This licence does not apply to logos or trademarks.

## **LIMITATION OF LIABILITY**


The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.


When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

This log has been contributed to the Queensland Geotechnical Database with the permission of Arup.



		<h1>CORED BOREHOLE RECORD</h1>										HOLE <h2>BH5</h2>			SHEET 2 OF 2					
PROJECT      LANG PARK STADIUM REDEVELOPMENT															LOGGED BY      KDN DATE/S      18.10.00					
CONTRACTOR      SP & KF CHRISTENSEN					ANGLE      Vertical					GROUND LEVEL      ~RL 9.0m										
DRILL MODEL      JACRO 350					BEARING      -					LOCATION      See Figure 2										
MOUNTING      4x4 TRUCK					DIAMETER      50/75/100mm															
DRILLING			STRATA			MATERIAL DESCRIPTION										DISCONTINUITIES				
CASING RUN, REC. (%)	WATER	SAMPLE TEST	R.L.	DEPTH	LEGEND	ROCK TYPE Colour, Grain Size, Structure, Minor Components	WEATHERING	ESTIMATED ROCK STRENGTH			FREQUENCY (per m)	SPECIFIC			GENERAL DESCRIPTION  Planarity, Roughness, Coating, Infill					
			AHD	m				EL	M	EH		TYPE	ANGLE	THICKNESS (mm)						
				1																
				2																
				3																
				4																
				5																
				6																
				7																
				8																
				9																
				10																
				11																
				12																
				13																
				14																
				15																
				16																
				17																
				18																
				19																
				20																
				21																
				22																
				23																
				24																
				25																
				26																
				27																
				28																
				29																
				30																
				31																
				32																
				33																
				34																
				35																
				36																
				37																
				38																
				39																
				40																
				41																
				42																
				43																
				44																
				45																
				46																
				47																
				48																
				49																
				50																
				51																
				52																
				53																
				54																
				55																
				56																
				57																
				58																
				59																
				60																
				61																
				62																
				63																
				64																
				65																
				66																
				67																
				68																
				69																
				70																
				71																
				72																
				73																
				74																
				75																
				76																
				77																
				78																
				79																
				80																
				81																
				82																
				83																
				84																
				85																
				86																
				87																
				88																
				89																
				90																
				91																
				92																
				93																
				94																
				95																
				96																
				97																
				98																
				99																
				100																
NOTES 1) No groundwater encountered prior to washboring at 1.5m							TYPE OF DISCONTINUITY Jo JOINT Be BEDDING PLANE PARTING Fo FOLIATION PARTING Cl CLAY SEAM We WEATHERED SEAM Cr CRUSHED SEAM Sh SHEARED ZONE Qr QUARTZ SEAM					JOB <h1>12215</h1>								



**Borehole 5**

**3.0m - 5.8m**

**Box 1 of 1**