

COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "*(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence*". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

MAIN ROADS DEPARTMENT
PROJECT: ANZAC BRIDGE

ENGINEERING BORE LOG

Form 2321 (d)

(P) 7/3/78

Sheet 2 of 6

HOLE No. P2 (cont.)

REF. H4950

DATUM AND

SURFACE RL.

LOCATION

JOB No.

PROJECT No. 1/954

DATE

TYPE
OF
DRILLING

Hollow Auger

Depth
(m)

Casing

Depth
(m)

Coring

Depth
(m)Depth
(m)Depth
(m)

ENGINEERING PROPERTIES		STRUCTURE	CORE REC % R.Q.D	Depth & R.L. (m)	STRATA DESCRIPTION	
Tensile Strength	Defect Spacing				SOIL TYPE	LITHOLOGY
100	100		1 - 1%	150 10.0 (0.49)	SOIL TYPE CLAY (CONT.)	
				60 (0)		
				15.1 (0.73)		
				86 (0)		
				100 (0)		
				100 (0)		
				32.5 (A.33)		
					END OF LOG	

REMARKS

GEOL. GE APPR. 16.4.1978

SPT Core Loss WEATHERED Extension Moderately
Very weathered Windy NOTE