## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Housing and Public Works under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "(c) State of Queensland (Department of Housing and Public Works) 2020, licensed under the CC BY 4.0 Licence, prepared by Arup". This licence does not apply to logos or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/

This log has been contributed to the Queensland Geotechnical Database with the permission of Arup.

ARU	TEST PIT RECORD						3	SHEET 1	
PROJECT Lang Park Stadium Redevelopment						GGED BY	VL 25.10.0	o	
CONTRACTOR EQUIPMENT TYP	PE Back	T PLANT H thoe 428B 4x4	lire	EXCAVATION TYPE  LENGTH 2.8m  WIDTH 1m	GROUND LEVEL appro			x. RL 7.5m	
EXCAVATION		STRATA		MATERIAL DESCRIPTION	:	CONE	DITION	OBSERVATION	
SAMPLE, TEST, BIT, SUPPORT, ETC.	AHD B CHOULD SYMBOL		LEGEND	SOIL TYPE `Colour, Plasticity, Grain Size, Minor Components	TURE COLUMN		CONESIVE	SOIL ORIGIN, STRUCTURE, ETC.	
				Silty GRAVEL: light grey brown, fine to coarse gravel				FILL	
				·					
		0.50	000	boulder and gravel rockfill material approximately 1m thick					
	+		000						
-	-1	:		<u></u>				-	
		1.50		CLAY: grey and brown, medium plasticity	-			RESIDUAL	
-	+2			-	-			-	
					_				
				-					
				tragments of glass and metal sheets in a slity gravel matrix					
				·	_			·	
1 105.50									
A AND A		3,80		ENDS TP3 @ 3.8m	-				
NOTES									
1) No groundwater encountered during excavation. 2) Edge of earthmound behind McCauliff stand. Slope of 45 degree. Excavation depth measurements taken from midpoint of pit								12215	