## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/



Project No. FM2055

Water Table 1.500

Start Depth 0.000

2.660

11.200

Surface RL

Refusal

## REPORT ON CONE PENETROMETER TEST

Client MAIN ROADS - GATEWAY UPGRADE PROJECT TEAM

Project GATEWAY UPGRADE


Job Ref.

Location E 9350.03 N 169871.28 SET DATUM

Chainage

Sounding CPTU107 Test Date 7/06/2004

Remarks



Date 7/07/2004 Cone ID 3167 Factor "a" 0.580 Checked Factor "b" 0.014 NATA Accreditation Number 2302 Test Method NATA Endorsed Test Report Q151A This document may not be reproduced except in full. Signatory Report No. FM2055/CPTU107/Q151A

Program Version 4.03b (32bit)