

## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "*(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence*". This licence does not apply to the Queensland Government logo or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

REPORT ON  
ELECTRIC FRICTION-SLEEVE CONE PENETROMETER  
Test Method No. QMRD 151(B)



MAIN ROADS  
Materials Branch, Herston  
Geomechanical Services  
REPORT No.2-407SE 918

PROJECT GATEWAY ARTERIAL

SOUNDING No. CP64

REF. No. SE 918

LOCATION E 42300.304, N 44331.093  
at approx. Ch. 5577.5


DATUM AHD

SURFACE RL 1 m

JOB No. C13A/7260/1

PROJECT No. 2-407

DATE 4/9/89



This laboratory is registered by the  
National Association of Testing Authorities,  
Australia. The tests reported herein have  
been performed in accordance with its  
terms of registration. This report may  
not be reproduced except in full.

CHECKED BY QPM DATE 20/12/89  
SIGNATORY QPM DATE 21/12/89  
D. F. Marks